

तथ्यहरू र चित्रहरू



क्षति स्थिति - निजी संरचना

घरहरूका प्रमुख प्रकार

प्रकार	पालिका	जिल्ला
ढुंगा र माटोको गारो	७२.५४%	८९.३८%
ईट्टा र माटोको गारो	२१.२२%	२.४७%
आर.सि.सि. फ्रेम	२.६०%	०.९३%
ईट्टा र सिमेन्टको गारो	१.०५%	०.६६%
अन्य	२.५९%	६.५९%

केन्द्रीय तथ्यांक विभाग, भुक्तमिय क्षति मूल्यांकन सर्वेक्षण, २०१५

आवासीय पुनर्निर्माण तथा प्रबलीकरण सम्बन्धि अध्यावधिक जानकारी

पुनर्निर्माणको स्थिति

कुल योग्य घरधुरी	८०४
अनुदान सम्झौता	७९८
पहिलो किस्ता	७९८
दोश्रो किस्ता	४२९
तेस्रो किस्ता	१३७

घरहरू

निर्माणाधीन: २८४

निर्माण सम्पन्न: १३७

प्रबलीकरणको स्थिति

कुल योग्य घरधुरी	१२
अनुदान सम्झौता	४
पहिलो किस्ता	४
दोश्रो किस्ता	१२

गुणासाहरू

दर्ता गरिएका: ०

सम्बोधन गरिएका: १९

मापदण्ड विपरितको मुद्दाहार

दर्ता गरिएका: ७२

सम्बोधन गरिएका: ३८

तथ्यांक अध्यावधिक: ०४/२०/२०७६

साझेदार संस्थाको उपस्थिति

क्रियाशील: साझेदार संस्थाको अभिलेख नभएको

परियोजना सम्पन्न भएको: साझेदार संस्थाको अभिलेख नभएको

निर्माण सामाग्रीको अवस्था

सामाग्री	ईकाई	आवश्यक मात्रा	उपलब्ध	लागत (नेरू)
ढुंगा	मि ३	१५,२५९	-	३,०००
गिट्टी	मि ३	१४,५९९	-	४,५००
बालुवा	मि ३	१,६९९	-	६,०००
काठ	क्युबिक फिट	१,८३०	-	-
सिमेन्ट (पिपिसि)	बोरा	-	-	७८०
सिमेन्ट (ओपिसि)	बोरा	४८,४५५	-	९००
छड	केजी	१,६७,३३८	-	८४
जस्ता	बण्डल	१,९८०	-	-
ईट्टा	थान	२,५८,९०९	-	२०

कामदारको प्रकार

- तालिमप्राप्त डकर्मो
- श्रमिक

औसत दैनिक ज्याला (नेरू.) शिर्षक

१,४०० /-
९५० /-

अन्य क्षेत्र



विध्यालयहरू

क्षतिग्रस्त: ३१
निर्माणाधीन: १५
निर्माण सम्पन्न: १५

स्वास्थ्य चौकी शिर्षक

क्षतिग्रस्त: -
निर्माणाधीन: -
निर्माण सम्पन्न: -

प्रमुख सम्पर्कहरू

पालिका कार्यालय

शिव कुमार गिरी
मेयर
९८५६०५४४९०

पालिका कार्यालय

रमेश बज्जरा
सम्पर्क व्यक्ति
९८५६०५५६८३

पालिका कार्यालय

विमला श्रेष्ठ
उप मेयर
९८५६०५५६०६

अनुदान व्यवस्थापन तथा स्थानीय पूर्वाधार

प्रबिन ढकाल
जिल्ला आयोजना कार्यान्वयन ईकाई-प्रमुख
९८५६०४००६०

पालिका कार्यालय

मोहन कुमार श्रेष्ठ
प्रमुख प्रशासकिय अधिकृत
९८४१६३२७९३

डि.एल.पि.आइ.यु.भवन

ऊमेश चौधरी
जिल्ला आयोजना कार्यान्वयन ईकाई-प्रमुख
९८५६०८४७३५

प्राविधिक कर्मचारीको अवस्था

कर्मचारी	उपलब्ध संख्या	थप आवेदनको संख्या
प्रविधिकहरू	१	-
उप-प्राविधिकहरू	१	-
सहायक उप-प्राविधिकहरू	१	-
डकर्मीहरू	- (७ दिने) - (५० दिने)	- (७ दिने) - (५० दिने)

श्रोत: पालिकास्तरीय सर्वेक्षण

डकर्मी तालिम


तालिमहरू (# कूल आवश्यक)

७ दिने तालिम

५० दिने सिपमुलक तालिम




पुरेको



बाँकी

श्रोत: एच.आर.आर.पि.को विश्लेषण

टि.ए. क्रियाकलापहरूको नक्शांकन



बारम्बार सोधिने प्रश्नहरू

प्रश्न: निजी अवासीय पुर्ननिर्माण अनुदानमा सूचीकृत हुन के के कागजातहरू पेश गर्नुपर्दछ ?

उत्तर: पासपोर्ट साइजको फोटो २ प्रति, सक्कल लालपूजा र नागरिकता सहित प्रतिलिपी १-१ प्रति । गाउँपालिका / नगरपालिकाका अधिकारीले थप जानकारी तथा सहयोग प्रदान गर्नेछन् । घरधनीले गाउँपालिका / नगरपालिकामा आफ्नो नाम सूचीकृत गर्न सक्नेछन् ।


प्रश्न: के हामीले निरीक्षण गर्न वा प्राविधिक सहायता प्रदान गर्न आएका सरकारी इन्जिनियरहरूलाई सेवा शुल्क तिर्नुपर्दछ?

उत्तर: पर्दैन । तपाईंले निरीक्षण गर्न वा प्राविधिक सहायता प्रदान गर्न आएका इन्जिनियर वा अन्य कर्मचारीलाई कुनै शुल्क तिर्नुपर्दैन । यदि कुनै कर्मचारीले निरीक्षण वा प्राविधिक सहायता प्रदान गरे वापत तपाईंसँग शुल्क माग्छ भने तुरुन्तै गाउँपालिका वा नगरपालिकामा सूचना दिनुपर्दछ ।

थप जानकारीका लागि १. रिजन गजुरेल (संयोजक) २. बिरेन शाह (प्राविधिक संयोजक) ३. रिजन गजुरेल (सूचना ब्यवस्थापक अधिकृत)

९८५१११४९३७ ९८१७३९६८५२ ९८५१११४९३७

FACTS AND FIGURES



Damage Grade (1-2)
988

Damage Grade (3-5)
827

Damage Status - Private Structures

MAJOR HOUSING TYPOLOGIES

Typology	Municipal	District
Stone and Mud Mortar Masonry	72.54%	89.38%
Brick and Mud Mortar Masonry	21.22%	2.47%
Reinforced Cement Concrete (RCC) Frame	2.60%	0.93%
Brick and Cement Mortar Masonry	1.05%	0.66%
Others	2.59%	6.59%

CBS damage assessment survey, 2015

HOUSING RECONSTRUCTION & RETROFIT UPDATES

Reconstruction Status

Total Eligible HHs	804
PA Agreement	798
I st Tranche received	798
II nd Tranche received	421
III rd Tranche received	137

Houses

Under Construction: 284

Completed: 137

Retrofitting Status

Total Eligible HHs	12
PA Agreement	4
I st Tranche received	4
II nd Tranche received	12

Grievances

Registered: 0
Addressed: 19

Non-compliances

Registered: 72
Addressed: 38

Data Updated on: 2019-07-31 00:00:00

PO Presence

Active: No POs Reported

Phased Out: No POs Reported

OTHER SECTORS



Schools

Damaged: 31
Under Construction: 15
Construction Completed: 15



Health Posts

Damaged: -
Under Construction: -
Construction Completed: -

STATUS OF CONSTRUCTION MATERIALS

Materials	Unit	Req. Quantity*	Ava.	Cost (NRs.)**
Stone	m ³	15,259	Yes	3,000
Aggregate	m ³	14,519	Yes	4,500
Sand	m ³	1,619	Yes	6,000
Timber	cu. ft.	1,830	Yes	-
Cement (PPC)	Sack	-	Yes	780
Cement (OPC)	Sack	48,455	Yes	900
Rebars	kgs.	167,338	Yes	84
Tin	bundle	1,980	Yes	-
Bricks	pcs.	258,901	Yes	20

Types of Workers

1. Skilled mason
2. Labourer

Avg. daily wage (NRs.)

1,400 /-
950 /-

KEY CONTACTS

Municipal Office

Shiva Kumar Giri
Mayor
9856054490

Municipal Office

Bindu Koirala
Focal Person
9856055683

Municipal Office

Bimala Shrestha
Deputy Mayor
9856055606

DLPIU-GMaLI

Prabin Dhakal
DLPIU-Chief
9856040060

Municipal Office

Mohan Kumar Shrestha
Chief Administration Officer
9841632793

DLPIU-Building

Umesh Chaudari
DLPIU-Chief
9856084735

HHs WITH LAND ISSUES

No Reported Land Issues

STATUS OF TECHNICAL STAFF


Staff	Available Nos.	Additional Req. Nos.
Engineers	1	-
Sub-Engineers	1	-
Asst. Sub-Engineers	1	-
Masons	- (7 days) - (50 days)	- (7 days) - (50 days)

Source: Municipal survey

MASON TRAINING


Trainings (# out of total required)

7 days Training



Reached


50 days Vocational Training



Remaining

Source: HRRP Analysis

TA ACTIVITIES MAP



FAQs

Q: What documents are required for enrolment in the GoN housing reconstruction programme?

A: Two copies of passport size photos and original copy and photocopy of land ownership card and citizenship card. Local officials at the Rural / Urban Municipality will be able to provide information and support and households can enrol at the Rural / Urban Municipality.

Q: Do we need to pay the engineers when they come to conduct inspections or provide technical assistance?

A: No, you do not have to pay the engineers, or any other staff, conducting inspections or providing technical assistance. If any field staff request payment for conducting inspection or providing technical assistance you should report it to the Rural / Urban Municipality officials.

For further information 1. Rijan Gajurel (General Coordinator) 2. Biren Shah (Technical Coordinator) 3. Rijan Gajurel (Information Management Officer)
9851114937 9817396852 9851114937